

IN THE SPECIFICATION:

Please amend paragraph [0087] as follows:

In FIG. 12, when the main wire 56b is further pulled in the direction as shown by the arrow h, the brake wire 87b is further pulled in a direction as shown by an arrow j via the wire connecting member 92 and, at the same time, the throttle wire 54b, which is not yet pulled as viewed in FIG. 9, is initiated to be pulled in a direction as shown by arrow k. By the foregoing operation, the distal ends of the main wire 56b, brake wire 87b and throttle wire 54b are pulled in the directions shown by arrows h, j, k, respectively, which correspond to the same pulling direction.